





characteristics

material s. steel

304 type

gauge 16 (1.5 mm)

finish brushed

mounting system

02 built in, side mounting brackets .seamless welded

04 2" x 3/8" Ø plastic anchors

04 2" x ¼ Ø SCREWS

measures

Length:

triple station

шidth

heigth

71.0" (18 0 cm)

16.5" (42.0 cm)

10.0" (25.0 cm)

features

.uandaL resistant

.to be used in schools,

cuinics, hospitaus, etc.

www.stainlessad.com

4673 Osborne Dr, El Paso TX, EUA (915) 330-0092, (915) 330-0093







characteristics

materiaL s. steel

304 type

gaug∈ 16 (1.5 mm) finish brushed

measures

triple station 71.0" (18 0 cm)

width 16.5" (42.0 cm)

10.0" (25.0 cm) heigth

mounting system

02 built in, side mounting brackets .seamless welded

04 2" x 3/8" Ø plastic anchors

04 2" x ¼ Ø SCREWS

features

uandal resistant

.to be used in schools, cuinics, hospitaus, etc.

www.stainlessad.com


4673 Osborne Dr. El Paso TX, EUA (915) 330-0093, (915) 330-0093






SIDE VIEW


VIEWS



TOP VIEW



FRONT VIEW



www.stainlessad.com

4673 Osborne Dr, El Paso TX, EUA (915) 330-0093, (915) 330-0093



INCLUDED ACCESORIES

STRAINER

- -CONVENIENT STRAINER
- -DRILLED CAP TO AVOID OBSTRUCTION
- -BRASS SLIP AND LOCK NUTS



P-TRAP

-BRASS CHROME PLATED P-TRAP, WITH SS STRAINER CONECTION.



SCREWS AND WALL ANCHORS

- -4, $Z_{...}^{"} \times 3/8^{"} \not \square$ PLASTIC WALL ANCHORS
- -4, 2" x 1/4 " Ø SCREWS



- * FAUCET NOT INCLUDED
 - FAUCET HOLE IS SINGLE HOLE
- PRE-DRILLED AT 1 1/4" Ø (32 MM).
 * AVAILABLE FAUCET SINK FLAT BASE: 2.8" (7 CM)
- * PLEASE TAKE NOTICE.



INSTALLATION GUIDANCE

- ①PREPARE A 2" Ø DRAINAGE OUTLET AT 20.0" (51cm) HIGH FROM THE FINISHED FLOOR LEVEL.
- 2USING AN SPIRIT LEVEL, DRAW A LINE AT 35.4" (90 CM) HIGH FROM THE FINISHED FLOOR LEVEL, NEAR THE SIDES OF THE LAVAROTY. THIS LINE WILL MATCH WITH THE UPPER BACK OF THE LAVATORY.
- 3 MEASURE THE DISTANCE BETWEEN THE BACK KEY HOLES AND HELPED WITH THE 35.4" (90 cm) DRAWN LINE, DRAW THE KEY HOLES DRILL POSITION IN THE WALL.
- ♠□NGE MARKED THE KEY HOLES IN THE WALL, DRILL THEM WITH A 3/8" CONCRETE DRILL BIT, AND FIX THEM AFTER THE PLASTIC ANCHORS; LET A 2 MM GAP BETWEEN THE WALL AND THE SCREW HEAD, TO FIT THE LAVATORY.
- 5 HANG ON THE LAVATORY.
- (6) AFTER THAT, AND CONFIRMED THE P-TRAP FITS INTO THE WALL DRAINAGE, DRAW THE LOWER DRILL HOLES.
- ${f ar y}$ DRILL THEM WITH A 3/8" CONCRETE DRILL BIT.
- 8 INSTALL FAUCETS, AND P-TRAP.
- * FAUCET NOT INCLUDED
- FAUCET HOLES ARE SINGLE HOLES PRE-DRILLED AT 11/4"Ø (32 MM).
- * AVAILABLE FAUCET SINK FLAT BASE: 2.8" (7 CM)
- * PLEASE TAKE NOTICE.
- * IF YOU NEED SPECIAL DRILL HOLES, OR SPECIAL LAVATORY SIZE; PLEASE LET US NOW, BEFORE PURCHASE.

FIG. 01 S OR **BRICK-WA** Σ (170 MOUNTING 67 STRONGLY SUGGEST FAL 7 _/w 1 TOTAL HEIGHT <u>0</u> _4 Ŋ ***WE *FFL: Finished Floor Level

CLEANING AND MAINTENANCE

THE 304 STAINLESS STEEL-FEED GRADE TYPE, NEEDS LESS MAINTENANCE THAN OTHER METALS, AND DOES NOT PRODUCE STAINS BY IT SELF OR BY THE SOLE WATER EXPOSURE, ALTHOUGH REGULAR CLEANING WILL PREVENT IT TO GET STAINED BY THE DIFFERENT CORROSIVE AGENTS, SUCH AS CHLORINE, SALT AND MINERALS DEPOSITS LEFT BY EVAPORATED WATER, ETC. THE FOLLOWING ARE INSTRUCTIONS IN ORDER TO KEEP YOUR STAINLESS STEEL LAVATORY APPERANCE AND FUNCTIONS PRESERVED.

- 1. ONLY USE WATER AND PLASTIC SCOURER TO CLEAN THE STAINLESS STEEL SURFACE, IF NEEDED, USE DISH SOAP, AND RINSE ANY RESIDUE.
- 2. DO NOT USE CHLORINE OR ANY PRODUCT WHICH INCLUDES IT, SINCE IT IS CORROSIVE TO METALS AND CAN DAMAGE THE STAINLESS STEEL SURFACE APPERANCE AND EVEN THE STRUCTURE. IF CHLORINE USE IS UNAVOIDABLE; PLEASE RINSE IT COMPLETELY, AND CLEAN ALSO THE EXTERNAL LAVATORY SURFACE. CHLORINE DROPS CAN STAIN OR EVEN CORRODE STAINLESS STEEL. AVOID CHLORINE TO LEAK IN THE LAVATORY BACK BY SEALING IT IN THE COUNTERTOP. A COMMON SITUATION IS TO SPLASH CHLORINE FROM THE FLOOR WHILE MOPPING, SO BE AWARE OF CLEANING ALL CHLORINE, IF MOPPING
- 3. DO NOT USE SHARPENED OBJECTS TO CLEAN THE STAINLESS STEEL SURFACE, SINCE THIS WILL BRING ABOUT SCRATCHES.
- 4. DESPITE STAINLESS STEEL NEEDS LESS MAINTENANCE THAN OTHER METALS, IF YOU CLEAN UP AND DRY IT COMPLETY ONCE ON A DAILY BASIS, OR AT LEAST TWICE A WEEK; THE STAINLESS STELL APPEREANCE WILL LAST FOR LONGER TIME.

